


1. PLD-10 mounting bracket (ref. 24375)
2. Screw
3. Lighting fixture
4. 12 V / 24 V power supply

*The full range of accessories and electronics is available at www.KlusDesign.eu

NOTE! All LED tapes must be connected to a 12 V or 24 V power supply.


IMPORTANT: Not all possible mounting procedures are presented here. More mounting procedures and related accessories can be found at www.KlusDesign.eu. Drawings of extrusions and accessories in these instructions are simplified and only approximate the actual shapes.




Screw the mounting brackets PLD-10 (1) to the surface with bolts (2).

NOTE! Use bolts suitable for the selected surface. The bolts must not exceed 3 mm / 0.12" in diameter and must have a countersunk head.

Number of the mounting brackets: 2 for 1 m, 4 for 2 m, 5 for 3 m of the profile length.



Connect the lighting fixture (3) to the 12 V / 24 V power supply (4) and mount it in the mounting brackets.



The lighting fixture can be rotated in the mounting brackets.